

5910-A

OPERATING INSTRUCTIONS

SOILMOISTURE METER

REV 10/90

Depress red button to insert
Soilmoisture Blocks leads

Insert leads in
angled slot

Digital Display

Read
Blocks
Button

STEP 1

Depress "Set Button" and move "adjusting Knob" until display reads 100. Pushing up on knob lowers the reading. Pushing down on knob increases the reading.

STEP 2

After inserting Soilmoisture Blocks Leads, depress "Read Button". Read Display

Adjusting Knob


Press
To Set
Button




Stainless Steel Belt
Clip for carrying convenience in the field.

For Battery Replacement remove 4 corner screws.

Side View



Back View



Replacement Battery
Soilmoisture Cat. No.
MEB001 or #216, 9V,
Transistor Battery.

SOILMOISTURE EQUIPMENT CORP.

P.O. Box 30025
Santa Barbara, CA 93105
U.S.A.

Telephone No. 805-964-3525 • Telex No. 65-8424 • Fax No. 805-683-2189 • Cable Address: SOILCORP

